

MISSOURI DEPARTMENT OF HEALTH AND SENIOR SERVICES STATE PUBLIC HEALTH LABORATORY BREATH ALCOHOL PROGRAM DATAMASTER MAINTENANCE REPORT

RECEIVED 3/6/14-CD

RECEIVED

· 被照》 DATAIV	IASTEN MAINTE	NANCE REP	OHI			By Carol Day	at 3:46 pm, Apr 01	1, 2014
Complete this report a Complete this report we Retain the original and	vhenever the instrum	ent is serviced o	r repaired	and whenever it is	s placed into	35 days). service.		
DATAMASTER SN 204080	NAME OF AGENCY MSHP E				02/28/20			
LOCATION OF INSTRUMENT (S 216 N. Missouri Str		ouri 63755			TIME OF INSPE			
CHECKLIST: Place a			o be satisfa	actory or if operation			(Write in observed	values
where determined.) U	nmarked items must	be corrected bef	ore using i	nstrument.	<u> </u>		(,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	raidoc
☑ DIAGNOSTIC CH	IECK (PRINTOUT AT	TACHED)		DATE AND TIME	(from printou	ut) 2-28-14	11:14 AM	
☑ COMPUTER				☑ DETECTOR				
✓ PROGRAM				FILTERS				
☑ HEATERS SA	MPLE CHAMBER _	49	°C	QUARTZ STA	NDARD			
☑ FLOW DETEC	TOR			☑ CALIBRATION	V			
PUMP HIGH S	SPEED			✓ PRINTER				
☑ INDICATOR LIGH	ITS				4			
SIMULATOR SOL	UTION SUPPLIER	RepCo Marketii	ng	LOT #	13001	EXP. DA	ATE 03/17/2015	
SIMULATOR TEN	1P (34°C ± 0.2°C)	33.99	_ °C SIM	ULATOR SN	1098		ATE 02/20/2014	
☑ CALIBRATION CH	ECK – (ONLY ONE :	STANDARD IS T	O BE USE	ED PER MAINTEI	VANCE REP			
Run three tests us	ing a standard solution	on. All three test	s must be	within ±5% of the	standard val		have a spread of .	005 or
0.100% STAND 0.080% STAND	DARD - MUST READ DARD - MUST READ DARD - MUST READ	BETWEEN 0.09 BETWEEN 0.07	95% AND 0	.105% INCLUSIV .084% INCLUSIV	E E			
TEST 1 • .103		TEST 2 .10			TEST 3	.103		
PERFORM R.F.I. T	EST (PRINTOUT AT	TACHED)						
INDICATE THE NUME (DO NOT INCLUDE S	ER OF BREATH TE ELF-ADMINISTEREI	STS IN THE FO	LLOWING	RANGES SINCE	THE LAST I	MAINTENANC	CE REPORT:	
	i04) 0	1	0 (.	1014) 0	(.1519)	2	OVER .19	1
LIST ANY NEW PARTS AND DES	CRIBE ANY ALTERATION OR	Notice supple			183			DIMITS
(USE OTHER SIDE IF NECESSA	RY).						WIS WITH ESTABLISHED	DEIMITS
INSPECTING OFFICE	Right Mark Company						AND DESIGNATION OF THE STATE OF	
SIGNATURE M	100			PRINT FULL N		MOI	UD 5 05	
TYPE II PERMIT NUMBER EXPIR	ATION DATE			TELEPHONE N		ergeant, MSI	HP E-05	
220278	09/15/2	2014		(573) 84				
RETURN COMPLETED REP	28	reath Alcohol Pro 375 James Blvd. oplar Bluff, MO 6		Department of H	ealth and Ser	nior Services,	Southeast District	Office

CERTIFICATE OF ANALYSIS

MANUFACTURER AND SUPPLIER: RepCo Marketing, Inc. EXPIRATION DATE: March 7, 2015 at 11:59 p.m.

RepCo Marketing, Inc. manufactured, tested and supplied Lot Mumber and Italian of Alcohol Certified Solution for simulators. Random samples of said lot number were analyzed by an independent laboratory utilizing a gas chromatograph and found to contain 1215 gms/dl +/-.003 gms/dl wt/vol ethanol (95% Confidence).

The alcohol and distilled water used in the solution were found to be free of any interferring substance.

This solution will produce a varor alcohol relue of 100 11200

This solution will produce a vapor alcohol value of .100 +/-3% gms/210L Breath when heated to 34 Degrees Celsius +/-0.2 Degrees Celsius in a simulator (95% Confidence).

The date of manufacture for this lot number is March 8, 2013

The expiration date for this lot number is March 7, 2015
at 11:59 p.m.

This document is a true representation of the original Certificate of Analysis.

Cecil B. Garner, President RepCo Marketing, Inc. Form RM 02

Face This Side Down - This Edge In First

BAC DataMaster Evidence Ticket

BAC DATAMASTER SERIAL NUMBER 204080 MISSOURI STATE HIGHWAY PATROL 82/28/14

HRREST TIME: 09:00

SUBJECT MAME: RADIOAEST

STATE/D.L.: MO/1234567890 DOB: 11/11/11

ARRESTING OFFICER:

に対応に予

OFFICER I.D.: 1161 TESTING OFFICER:

OFFICER I.D. 田田の

EXPIRATION DATE: 89/15/14 PERMIT NUMBER: 228278

MISCELLANEOUS DATA: RADIO TEST --- BREATH ANALYSIS

WERIFIED , MAG INTERNAL STANDARD

BLANK TEST

RHINIO INTERFERENCE

Face This Side Down - This Edge In First

BAC DataMaster Evidence Ticket

BAC DATAMASTER SERIAL NUMBER 204080 MISSOURI STATE HIGHWAY PATROL 02/28/14

--- DIAGNOSTIC CHECK ---

COMPUTERS

と出る

SKAY. PROGRAM (84-87-2989):

HEATERS

SHAPLE CHRIBER:

100 A

FLOW DETECTOR:

OKAY

HIGH SPEED:

以出 DETECTORS

OKAY. FILTERS:

OKAY QUARTZ STANDARD:

OKAY

CALIBRATIONS

!"#\$%&'<>***.-./8123456789:;<=>?@ABCDEFG HIUKLMNOP@RSTUVWXYZ[\]^ 'abcdefahijklmno PRINTER TEST Darstuvwxuz(|)+-

Operator Signature_

Operator Signature_

BAC DataMaster Evidence Ticket

MISSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL NUMBER 204080 02/23/14

TESTING OFFICER:
LYNCH/M
UFFICER I.D.: 1161
PERMIT NUMBER: 220278
EXPIRATION DATE: 09/15/14
MISCELLANEOUS DATA:

--- SUPERVISOR MODE ---

(T)	01:11	Ξ (U	OU:TT	~ (U	eri CU ss eri eri	11:20	1:20
(S)	VERIFIED	(n) (5) (7)	. 668	 (3)		(*) (<u>S</u>)	
BLANK TEST	INTERMAL STANDARD	EXTERNAL STANDARD	BLAK JENT	EXTERNAL STANDARD	BLENK TENT	EXTERNAL STANDARD	MINE TENT

AWG. = 183

Operator Signature 1



Governor

Jeremiah W. (Jay) Nixon

Missouri Department of Health and Senior Services

P.O. Box 570, Jefferson City, MO 65102-0570 Phone: 573-751-6400 FAX: 573-751-6010 RELAY MISSOURI for Hearing and Speech Impaired 1-800-735-2966 VOICE 1-800-735-2466

Margaret T. Donnelly



Missouri Department of Health and Senior Services Breath Alcohol Program

SIMULATOR CALIBRATION REPORT

Senior Services, 19 CSR 25-30. accordance to the standards set by the Rules of Missouri Department of Health and standards traceable to the National Institute of Standards and Technology (NIST) in This is to certify that the simulator listed below has been examined and tested using

Reference Temperature 34.01 This calibration v	Simulator Temperature 34.00	26.01 O° 10.0+ dir	ĀЕЗ <mark>Iu Tolerance</mark>
,		CYFIBI	RATION RES
Model Number:	3407C		
Manufacturer:	RepCo		
Serial Number:	8670		
Адепсу:	S iruossiM	wdgiH ətat	ay Patrol
	7	YTOWIS	LOK INKOKI

COPY OF CALIBRATION STICKER

Brian M. Lutmer

This simulator has been calibrated according to DHSS specifications

02/18/2014

304447

Lttt0£ £107/81/70 02/18/2015

BMT

O 10.0+

STATTINI TRYLALS: SV18 NIST REF. THERM. SERLAL NO: DATE OF CALIBRATION: EXPIRATION DATE: SIMILLATOR SERIAL NO.: 0298



This calibration was performed:

This calibration was performed by:

VIST-Traceable Thermometer SN: